
50X1-HUM Sanitized Copy Approved for Release 2011/05/25: CIA-RDP82-00457R010700180002-6 CHNICK HATELIGENCE AGENCY REPORT INFORMATION REPORT CD NO 91 E DISTR. To Mar 1952 PENTO Polard Railroad Information NO OF PAGES SUBJECT PLACE **ACQUIRED** SUPPLEMENT TO CIRCULATE DATE OF REPORT, NO. 50X1-HUM INFO. COMPANY OF A CONTRACT OF A STATE OF THIS DOCUBERS CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE
OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIOMS 793
AND 794, OF THE C. S. COOD, AS AMENDED. ITS TRANSMISSION OR REVEAL
ATION OF ITS CONTENTS TO ON RECEIPT BY AN UNMUTHORIZED PERSON
IS PROHIBITED BY LAW THE REPRODUCTION OF THIS FORM IS PROHIBITED. THIS IS UNEVALUATED INFORMATION 50X1-HUM 1. A commission consisting of three Polish officers, a representative of the Polish Railways' Directorate and the manager of the Pila operational (railroad) traffic arrived at the Pila (Schneidemthl-P54/S04) railroad station in September 1951. They examined the operational departments of the station, including the condition of machinery, whether the machinery was being untilized to capacity, and whether there was any surplus machinery. They furthermore investigated the stocks of spare parts and the stocks of coal and oil. 2. Of the 17 existing rater cranes, only 10 were in operation. An instruction was issued to put those out of repair immediately into working condition. Damaged and obsolete passenger and freight cars were also inspected. Part

- 2. Of the 17 existing water cranes, only 10 were in operation. An instruction was issued to put those out of repair immediately into working condition. Damaged and obsolete passenger and freight cars were also inspected. Part of these were to be sent to the main repair works at Poznan (P53/X26). It was significant that the Commission inspected and examined the capacity of the kitchen equipment in the railway canteens, the railroad men's duty sleeping quarters, and the railway restaurant. A survey was also made of the distance between these installations and the tracks.
- 3. According to a confidential memorandum at the end of August or the beginning of September 1951 issued by the Railways' Directorates at Gdansk (Q55/Yh2) and Poznan, all railroad stations which had rescue trains at their disposal were to hand over some of the ambulance cars. The station subordinate 50X1-HUM to the above Directorates were ordered to dispatch the ambulance cars to Bydgoszcz. There they were formed into trains and sent to Lublin. In addition, the stations were instructed to send to Byogoszcz surplus camp beds from the inventory of the railwaymen's duty sleeping quarters. In accordance with the above order, Pila Railway Station sent an ambulance car and lh surplus camp beds to Bydgoszcz in September 1951.

TATE	X NAVY	X NSRB	CUML	CISTRIBUTION				
RMY	AIR	NSRB FBI	Ph.					
•	· · · · · ·				No Ch	Decument No		
					4			



50X1-HUM

-2-

A new tranship station was under construction in September 1951 at Hurko (\$50/V55), approximately seven kms. east of Przemysl. The work was being conducted by the PPRK #9 (Panstwowe Przedsiebiorstwo Robot Kolejowych - Railway Works State Enterprise), a "Service for Poland" brigade (five companies) and civilian workers. The earth works were nearing completion and construction of loading ramps had begun. A branch line has been laid from the Russian broad gauge and normal gauge Przembysl - Medyka line; a large quantity of rails and sleepers was brought to the spot. Construction of administration buildings had not yet started.

50X1-HUM		
JUN I-I IUIVI		
1		
t		

CONFICIALS ONLY